

**Site:** Land rear of Durham Court

**Survey date:** 08/03/2024

**Surveyor:** Peter Davies

## Tree Survey Schedule



Tree ref.	Species	Height (m)	Stem diameter (mm)	Branch spread (m)	Crown clearance (m)	Age class	Physiological condition	Structural condition	Comments	Preliminary management recommendation	Category grading	Root Protection Area (m <sup>2</sup> )	Root Protection Radius (m)
T1	Sycamore (Acer pseudoplatanus)	14	400 est	N: 2 E: 2 S: 5 W: 4	Crown: 2 south Branch: 2 south	Mature	Fair	Good	Third party tree viewed from site. Asymmetric crown due to suppression from removed tree. Minor dead wood at top of crown. Previously crown lifted.	No action required on date of survey.	B1+2	72.4	4.8
T2	Sycamore (Acer pseudoplatanus)	14	450 est	N: 4 E: 2 S: 3 W: 5	Crown: 2 west Branch: 3 west	Mature	Good	Good	Third party tree viewed from site. Secondary stem from 2m. Asymmetric crown. Previously crown lifted. Minor dead wood.	No action required on date of survey.	B1+2	91.6	5.4
T3	Sycamore (Acer pseudoplatanus)	14	400 est	N: 2 E: 3 S: 3 W: 5	Crown: 2 west Branch: 2 west	Mature	Good	Good	Third party tree viewed from site. Multi-stemmed from approximately 1.5m. Drawn u growth habit. Previously crown lifted. Minor dead wood.	No action required on date of survey.	B1+2	72.4	4.8
T4	Ash (Fraxinus excelsior)	17	450 est	N: 3 E: 7 S: 5 W: 4	Crown: 7 average Branch: 3 north	Mature	Good	Poor	Potentially third party tree (straddles fence line). Dual stemmed from 2m. West stem partially split at primary union at 6m. East stem overhangs offsite parking area. Understorey and fence inhibit inspection of stem.	Pollard to approximately 5m (ownership of tree needs to be established).	C2	91.6	5.4
T5	Ash (Fraxinus excelsior)	19	340	N: 3 E: 3 S: 2 W: 33	Crown: 10 north Branch: 10 north	Mature	Good	Fair	Third party tree. Drawn up growth habit and high crown clearance.	No action required on date of survey.	B2	52.3	4.1
T6	Sycamore (Acer pseudoplatanus)	19	400, 380, 270	N: 4 E: 7 S: 2 W: 1	Crown: 4 east Branch: 4 east	Mature	Good	Fair	Third party tree. 1m bark inclusion between primary stems. Asymmetric crown bias east. Moderate pruning wounds with some minor cavities on stems.	No action required on date of survey.	B2	170.7	7.4

**Site:** Land rear of Durham Court

**Survey date:** 08/03/2024

**Surveyor:** Peter Davies

## Tree Survey Schedule



Tree ref.	Species	Height (m)	Stem diameter (mm)	Branch spread (m)	Crown clearance (m)	Age class	Physiological condition	Structural condition	Comments	Preliminary management recommendation	Category grading	Root Protection Area (m <sup>2</sup> )	Root Protection Radius (m)
G7	Mixed (sycamore x2, ash x2)	10 average	Up to 260 average	N: 3 E: 4 S: 3 W: 2	2-4 average	Semi mature	Good	Fair	Row of four third party trees adjacent to offsite car park. Multi-stemmed. Likely self seeded. Previously crown lifted. Two ash conflict with fence.	No action required on date of survey.	C2	30.6 average	3.1 average
G8	Mixed shrubs (common myrtle dominant)	1-3 average	Up to 150 average est	1-2 average	0 average	Mature	Fair	Fair	Mixed, offsite shrubs. Dieback on north side of group.	No action required on date of survey.	C2	10.2 average	1.8 average
T9	Blue spruce (Picea pungens)	9	260	N: 2 E: 2 S: 2 W: 2	Crown: 2 average Branch: 2 average	Semi mature	Good	Good	Typical example of species. Previously crown lifted.	No action required on date of survey.	B1+2	30.6	3.1
T10	Sycamore (Acer pseudoplatanus)	13	820 over ivy at 1m	N: 6 E: 7 S: 5 W: 6	Crown: 2 west Branch: 2 west	Mature	Good	Good	Third party tree. Dense ivy on stem and primary crown structure. Small dead wood due to suppression. No major visible defects.	Sever ivy around base of stem (suggestion only as third party tree).	A1	304.2	9.8
G11	Elder (Sambucus nigra)	2-4 average	Up to 150 average est	1-4 average	0-1 average	Semi mature-mature	Fair	Fair	Third party area of elder shrubs. Most ivy clad.	No action required on date of survey.	C1	10.2 average	1.8 average